

SHUSHRUSHA HOSPITAL

BANGALORE
20/06/2019

 SHUSHRUSHA HOSPITAL
ಶುಶ್ರೂಷಾ ಆಸ್ಪತ್ರೆ



 SHUSHRUSHA HOSPITAL

Clinical Services	Emergency Services
<ul style="list-style-type: none">• General Medicine• Pediatrics• Gynecology & Obstetrics• Dermatology• Ophthalmology• ENT• Orthopedics• Physiotherapy• Dental• Radiology• Laboratory	<ul style="list-style-type: none">• 24/7 Emergency• Accident & Trauma• Critical Care• ICU• Operation Theatre• X-Ray• Ultrasound• Laboratory

24/7

Project Snapshot

Name of company: Shushrusha Hospital

Total Area: 1000 Sq.ft

Industry: Reception area

City: Bangalore

Machine Installed & Quantity: PAC 18 – 01 Unit

Country: India

Symphony



PAC 18 Side Discharge Unit

We installed 01 unit of
PAC 18 Side discharge
machine.





Ducting – Machine is connected to 70 feet duct having 04 outlets.

PAC 18

PAC 18 Three side cooling pads offering superior cooling.

